

Oil Field Environmental Incident Summary

Incident: 20160915141659 **Date/Time of Notice:** 09/15/2016 14:16

Responsible Party: LIME ROCK RESOURCES III-A, L.P.

Well Operator: LIME ROCK RESOURCES III-A, L.P.

Well Name: REPETOWSKI 1-34-27H-143-98

Field Name: HUNGRY MAN BUTTE

Well File #: 20121

Date Incident: 9/14/2016

Time Incident: 02:03

Facility ID Number:

County: BILLINGS

Twp: 143

Rng: 98

Sec: 34

Qtr:

Location Description:

Submitted By: Rebecca Zent

Received By:

Contact Person: Rebecca Zennt
1111 BAGBY, SUITE 4600
HOUSTON, TX 77002

General Land Use: Pasture

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.5 Mile

Distance Nearest Water Well: 0.5 Mile

Type of Incident: Equipment Failure

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Gallons			0	gallons

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 9/26/2016

Clean Up Concluded: 9/15/2016

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

Effectuated well site surface, and adjacent pasture land.

Action Taken or Planned:

SM Fencing was dispatched to cut and bag the grass and cleanup the facility site.

Wastes Disposal Location: Chimney Butte

Agencies Involved:

Updates

Date: 9/15/2016 **Status:** Reviewed - Follow-up Required

Author: Crowder, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release impacted areas off location. Follow-up is required.

Date: 9/19/2016 **Status:** Inspection

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 1545. The area around the well pad has been mowed. Hydrocarbon smell or staining is not present. Standing water does not have a sheen. Cleanup is sufficient. No further action needed at this time.